



Traction Capital and Leasing, Inc. (Dakota Forgione)
2806 Reynolds Road, Winston Salem, NC 27106
(757) 544-6757

VIN: 3ALACWDT4FDGK6547

2015 FREIGHTLINER M2

SPECIFICATIONS	
MILEAGE	209,728 / 209,729 (ECM)
ENGINE HOURS	12,358
ENGINE	CUMMINS ISB 6.7L 280 HP
ENG BRAKE	NO
ENG SERIAL	58423791
FUEL / TANKS	DIESEL - 1 ALUM 75 GAL TOTAL
TRANSMISSION	ALLISON 2500 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 5.88
AXLE TYPE	SINGLE - F 12,000 LB / R 21,000 LB
GVWR	33,000
FRAME	STEEL
SUSPENSION	AIR RIDE
TIRE SIZE	295/75R22.5
WHEELS	F STEEL / R STEEL
REAR D TYPE	ROLL-UP
LIFT GATE MAKE	MAXON
LIFT GATE CAPAC (LBS)	2500
INTERIOR H (IN)	102
EXTERIOR W (IN)	102
EXTERIOR L (FT)	26.0
AIR COND	YES, OPERATIONAL
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD, OPERATIONAL
HIGH BACK SEATS	DRIVER SIDE ONLY
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



BRAKES	
LEFT FRONT	RIGHT FRONT
22	18
LEFT REAR 1	RIGHT REAR 1
24	24

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
20 / 32 FIRESTONE STEEL		20 / 32 FIRESTONE STEEL	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
17 / 32 FIRESTONE STEEL	18 / 32 FIRESTONE STEEL	20 / 32 FIRESTONE STEEL	20 / 32 FIRESTONE STEEL
FRONT TIRES: 295/75R22.5		REAR TIRES: 295/75R22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHT S WORK?	YES - ALL
OIL LEAKS?	NO	WIPERS WORK?	YES
WATER LEAKS?	NO	GAUGES WORK?	YES - ALL
OIL IN COOLANT?	NO	AIR HORN WORKS?	NA
CLUTCH PLAY?	NA	CITY HORN WORKS?	YES
STARTS?	YES	DIESEL PARTICULATE FILTER PASS	
DRIVES	YES		

WEAR & TEAR DETAIL

DIAGNOSTICS UNABLE TO RETRIEVE FULL DATA ON CAN/ECM FROM REPORT. NO WARNING INDICATORS ACTIVE AT DASH.

DIAGNOSTICS	UNABLE TO RETRIEVE FULL DATA ON SCAN (SEE ECM REPORT 1). NO WARNING INDICATORS ACTIVE AT DASH.
VAN BOX	RIGHT SIDE MANY DENTS AND LARGE CREASE AT THE TOP REAR WITH TWO PATCH REPAIRS. RIGHT REAR CORNER POST DENTED AT BOTTOM, LEFT SIDE HAS A FEW DENTS. FRONT LEFT CORNER OF VAN BOX HAS DAMAGE AT TOP
DOCK PLATE	REAR DOCK PLATE RIGHT SIDE STEPS ARE BENT.
POWER STEERING	GEARBOX LEAKING
DIFFERENTIAL	FLUID RESIDUE AT BOTTOM OF HOUSING
TOOL BOX	PAINT FLAKING AND RUST FORMING
SUSPENSION	STEER SHOCK LEAKING
PASSENGER SEAT	UPHOLSTERY IS TORN / CUT
INSTRUMENT CLUSTER	COVER IS CRACKED
HEADLINER	FABRIC IS DIRTY AND SAGGING.

REPORT PHOTOS





REPORT DOCUMENTS

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com